

The TRIUMPH Corporation

Parts - Tools - Accessories Bulletin

February 24, 1967

Bulletin No. 67-6P

PARTS CATALOGUE CORRECTIONS

Please make the following corrections in your parts catalogues immediately.

REPLACEMENT PARTS CATALOGUE NO. 8 FOR 1967 "C" RANGE MODELS

<u>Page No.</u>	<u>Ref. No.</u>	<u>Corrections</u>
31	9	ADD: 54419124 Cam for battery ignition models (new 160° type), fitted as standard equipment to all 1967 T100R models. ADD: 54415751 Sleeve and Action Plate for T100R. 54415747 Sleeve and Action Plate for T100C.
41	1 1	CHANGE: T1476 to T1476/18. NOTE: All sprockets listed are available from stock if gearing changes at the gearbox are desired.
43	11 ✓	NOTE: Correct part number for this stud is F3665.
51	8 & 9	DELETE: H2100 Top Lug, and H1527 Bonded Bushings. Not fitted to 1967 "C" range models. All 1967 "C" range models are fitted with the H2099 Top Lug as illustrated on page 52. H2100 Top Lugs and hardware for rubber mounted handlebars are stocked if this type of mounting is desired.
53	7	NOTE: H1696 Covers are stocked for use if headlight is removed, but are not fitted as original equipment to 1967 "C" range models.
59		NOTE: Although not fitted to U.S. models, many parts for Q.D. wheels are stocked. See page 57, #5 "B" range parts catalogue for parts stocked. <u>ONLY</u> the items for which prices are shown on the stick-on price list are available.
65	10	NOTE: F1717 Petrol Taps, although not fitted to 1967 T100 models as supplied to the Eastern United States, are available from our parts stock. This petrol tap is an excellent accessory to offer riders desiring a petrol tap incorporating a reserve fuel supply feature. Repair kits are also available for these petrol taps, Part No. CD480.
	15 & 16	NOTE: Parcel Grids and Mounting Screws are available from our parts stock for use on gas tanks supplied with tapped mounting holes.

-OVER-

February 24, 1967

-2-

Bulletin No. 67-6P

REPLACEMENT PARTS CATALOGUE NO. 5 FOR 1967 "B" RANGE MODELS

<u>Page No.</u>	<u>Ref. No.</u>	<u>Corrections</u>
27		ADD: 54415751 Sleeve and Action Plate for T12OR and TR6R. 54415747 Sleeve and Action Plate for T12OTT and TR6C.
49 and 51	10 3	NOTE: The correct part number for the new fork lock is F6738 as listed in the parts catalogue. The number F6728 in Bulletin No. 66-2P is a typographical error and should be corrected to F6738.

SPECIAL NOTE: Where it is stated in our correction bulletins that an item is "not fitted to U.S. models," this means ONLY that the part is not fitted at the factory to that particular range as supplied that year to the Eastern United States. These same parts may very well be fitted to other Triumph ranges, or may be available from our parts stock.

Let Bonny